

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program April 12, 2010

Reviewed:

28	14	T	2	
		1	7	
	, ,		1	

Mine Name: Italian TanPermit Number: S/007/0038Operator Name: Quality Building StoneInspection Date: 03/24/2010Inspector(s): Brett Gregory for Wayne WesternTime: 11:00 amOther Participants: NoneMine Status: Active

	Elements of Inspection	Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds			
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Concurrent Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8.	Water Impoundments			
9.	Soils			
10.	Revegetation			
11.	Air Quality			
12.	Other			

Bond Amount: \$12,500 **Permit fee**: Current

Purpose of Inspection:

The operator asked for an inspection to release the bond. At the time a full inspection was not intended nor planned for without the presence of the landowner and mine operator.

Inspection Summary:

The site appeared stable. Only two issues were noteworthy:

- 3) All road disturbances should have erosion control and post-mining land use maintenance.
- 10) Non-designated road disturbances and some small mining areas need to meet 70% revegetation standards. An approved seed mix should be determined by the Division and implemented by the mine operator.

(Photographs attached)



Inspection Date: 03/24/2010

Page 2 of 4 S/007/0038

Conclusions and Recommendations:

The landowner must assume in writing full responsibility for the non-reclaimed road before the bond can be released to the operator. Additional measures should also be taken by the operator to control the erosion found on site (i.e. installation of water bars, silt fences, berms, trenches, etc.). I would further recommend the entire road be seeded with the other disturbed areas in order to help stop the formation of reels and road ruts.

The operator should establish an additional inspection to take place with the landowner and lead inspector present. Reclamation details need to be established on site with all parties involved before bond release considerations can be made.


Inspector's Signature

BG; whw, ppb, vs

cc: Quality Building Stone, Inc. Enc. Seed-mix recommendation

P:\GROUPS\MINERALS\WP\M007-Carbon\S0070038-ItalianTan\inspections\insp-03252010.doc

Inspection Date: 03/24/2010 Page 3 of 4 S/007/0038



Inspection Date: 03/24/2010 Page 4 of 4 S/007/0038



Recommended Revegetation Species List for

Italian Tan Quarry \$/007/0038

Common Name	Species Name	Rate lbs/ac (PLS)
Hycrest crested wheatgrass Basin Wildrye Luna pubescent wheatgrass Boizoisky russian wildrye Indian ricegrass	Agropyron cristatum Elymus cinereus Agropyron tricophorum Elymus junceus Oryzopsis hymenoides	0.5 2.0 2.0 1.5 2.0
Ladak alfalfa Yellow Sweetclover Palmer penstemon	Medicago sativa Melilotus officinalis Penstemon palmerii	1.0 0.5 0.75
Wyoming big sagebrush 4-wing saltbush Rubber Rabbitbrush Forage Kochia	Artemisia tridentate wyomingens Atriplex canescens Chrysothamnus nauseosus Kochia prostrata	sis 0.1 2.0 0.5 0.75
	Total Seed	13.6 lbs/ac

^{*} Rate is recommended for broadcast seeding.